



Shape A-1



Shape A-2



Shape A-3



Shape A-4



Shape A-5



Shape A-6



Shape A-11



Shape A-12



Shape A-13



Shape A-14



Shape A-15



Shape A-21



Shape A-22



Shape A-23



Shape A-24



Shape A-25



Shape A-26



Shape A-31



Shape A-32



Shape A-34



Shape A-35



Shape A-36



Shape A-37



Shape A-38



Shape A-39



Shape B-41



Shape B-42



Shape B-43



Shape B-44



Shape B-45



Shape B-51



Shape B-52



Shape B-53



Shape B-55



Shape B-61



Shape B-62



Shape B-63



Shape B-71



Shape B-72



Shape B-73



Shape B-81



Shape B-82



Shape B-83



Shape B-91



Shape B-92



Shape B-93



Shape B-95



Shape B-96



Shape B-97



Shape B-98



Shape B-103



Shape B-104



Shape B-106



Shape B-111



Shape B-112



Shape B-113



Shape B-121



Shape B-122



Shape B-123



Shape B-131



Shape B-132



Shape B-134



Shape B-135

A1	19.05	31.70	6	W 146	03.18	12.70	3
A2	25.40	69.85	6	W 150	04.76	01.59	3
A3	22.23	31.75	6	W 151	04.76	03.18	3
A4	31.75	28.58	6	W 152	04.76	06.35	3
A5	19.05	44.45	6	W 153	04.76	09.53	3
A11	20.64	31.75	6	W 154	04.76	12.70	3
A12	17.46	28.58	6	W 155	04.76	15.88	3
A13	28.58	22.23	6	W 157	06.35	01.59	3
A14	17.46	24.99	6	W 158	06.35	03.18	3
A15	6.35	25.40	6	W 159	06.35	04.76	3 & 6
A21	25.40	15.88	6	W 160	06.35	06.35	3 & 6
A22	19.05	19.05	6	W 162	06.35	09.53	3 & 6
A24	6.35	25.40	6	W 163	06.35	12.70	3
A25	25.40	15.88	6	W 164	06.35	19.05	3 & 6
A26	15.88	19.05	6	W 167	07.94	06.35	3 & 6
A31	34.93	15.88	6	W 170	07.94	12.70	3
A32	25.40	09.53	6	W172	09.53	01.59	3
A34	38.10	09.53	6	W 173	09.53	05.18	3 & 6
A36	41.28	06.35	6	W 174	09.53	06.35	3 & 6
A37	31.75	25.40	6	W175	09.53	09.53	3 & 6
A38	25.40	19.05	6	W176	09.53	12.70	3 & 6
A39	19.05			W177	09.53	19.05	3 & 6
GROUP : B				W178	09.53	25.40	3 & 6
B41	15.88	15.88	3 & 6	W179	09.53	31.75	6
B42	12.70	19.05	3 & 6	W182	12.70	03.18	3 & 6
B43	06.35	07.94	3	W183	12.70	06.35	3 & 6
B44	05.56	09.53	3	W184	12.70	09.53	3 & 6
B45	04.76	07.94	3	W185	12.70	12.70	3 & 6
B51	11.11	19.05	3 & 6	W186	12.70	19.05	3 & 6
B52	09.53	19.05	3 & 6	W187	12.70	25.40	3 & 6
B53	06.35	15.88	3	W188	12.70	38.10	6
B55	03.18	06.35	3	W191	15.88	03.18	3 & 6
B61	19.05	07.94	3	W192	15.88	06.35	3 & 6
B62	12.07	09.53	3 & 6	W195	15.88	19.05	3 & 6
B63	06.35	04.76	3	W196	15.88	25.40	6
B71	15.88	02.38	3	W197	15.88	50.80	6
B72	12.70	03.18	3	W199	19.05	01.59	3 & 6
B73	12.70	03.18	3	W200	19.05	03.18	3 & 6
B81	19.05	04.76	3	W201	19.05	06.35	3 & 6
B82	12.70	06.35	3	W205	19.05	25.40	6
B83	09.53	03.18	3	W208	19.05	50.80	6
B91	12.70	15.88	3 & 6	W211	22.23	05.18	3 & 6
B92	06.35	06.35	3	W215	25.40	03.18	3 & 6
B93	04.76	04.76	3	W216	25.40	06.35	3 & 6
B95	03.18	04.76	3	W219	25.40	19.05	6
B96	03.18	06.35	3	W220	25.40	25.40	6
B97	03.18	09.53	3	W225	31.75	06.35	6
B98	02.38	06.35	3	W226	31.75	09.53	6
B103	15.88	04.76	3 & 6	W227	31.75	12.70	6
B104	07.94	09.53	3	W235	40.00	06.00	6
B106	03.18	02.78	3	W236	40.00	13.00	6
B111	11.11	17.46	3 & 6	W237	40.00	20.00	6
B112	09.83	12.70	3	W238	40.00	40.00	6
B113	06.35	06.35	3	W242	50.00	13.00	6
B121	12.70	12.70	3 & 6				
B122	09.53	09.53	3				
B123	04.76	04.76	3				
B131	12.70	12.70	3 & 6				
B132	00.53	12.70	3 & 6				
B134	07.94	09.54	3 & 6				
B135	06.35	12.70	3 & 6				
B136	06.35	07.94	3 & 6				

Note : Spindle Available
3 mm & 3.18 mm
6 mm & 6.35 mm